

# **MSPO CERTIFICATION**

## **PUBLIC SUMMARY REPORT**

**RICH AND SUCCESS SDN BHD**  
PPM 191, Elopura 90000, Sandakan, Sabah

MSPO NO: MSPO/2018/22

22/02/2020



**REHPRO CERTIFICATION SDN BHD**

Lot B5 -2C, Tingkat 5, Blok B,  
Peti Surat No 16, Bangunan KWSP,  
88598 Kota Kinabalu, Sabah.  
Tel : 088-222320  
Fax: 088-222420  
Email: [rehprogroup@gmail.com](mailto:rehprogroup@gmail.com)  
Website: [www.rehpro.com.my](http://www.rehpro.com.my)

### 1.1 Detail of Certification Assessment

Audit date(s)	04 January 2020
Type of audit	Initial Certification
Standard	Malaysian Sustainable Palm Oil MS 2530-3:2013 General principles for oil palm plantations and organized smallholders MS 2530-4:2013 General principles for palm oil mills
Scope	Production of Sustainable Crude Palm Oil and Palm Kernel

### 1.2 Organisation Information/ Contact Person

Name	TAN KEH CHAY
Position	ESTATE MANAGER
Address	PPM 191 ELOPURA, 90000 SANDAKAN, SABAH
Phone	016 6637670
Fax No	089 219418
Email	marktankc@yahoo.com

### 2.1 Audit Methodology

The assessment was conducted in 2 manday on **4th January 2020** involving 1 estate of **RICH AND SUCCESS SDN BHD**. The audit focused mainly on the conformance of the organization against the requirements of certification standard i.e. **MS 2530-3:2013 Part 3: General principles for oil palm plantations and organized smallholders**.

During the audit, audit team has visited the field, line site, workshop, chemical stores, waste collection areas and other surrounding facilities such as clinic, surau and canteen to verify the implementation of the **MSPO MS2530-3**. Interviews with the team management, employees, contractors and other relevant stakeholders. Apart from the above, records as well as other related documentation were also evaluated.

It is important to note that the finding from this audit is based on samples taken from the organization activities, procedures, records and interview. Statistically, there is always a possibility that one or more issues/areas will remain unidentified during the course of this audit. The absence of non-compliance in any area or activity does not necessarily imply that no lapses or non-compliance exist.

### 2.2 Audit objective

The audit objectives are as follows:

- a) To evaluate the organization conformance against the MSPO standards requirements.
- b) To determine the ability of the management system to ensure that the organization meets applicable statutory, regulatory and contractual requirements
- c) To determine the effectiveness of the management system to ensure that the organization can reasonably expect to achieving its specified objectives
- d) To identify areas for potential improvement of the organization management system (if applicable)
- e) To make appropriate recommendations based on the assessment findings.

**2.3 Audit Team**

Lead Auditor	Ahmad Kamal Bin Shahabuddin
Co- Auditor	Gusman b. rudin
Auditor in- training	-
Technical Expert	-
Observer	-

**2.4 Stakeholder Consultation**

Stakeholder consultation was initiated with the announcement in the REHPRO web site. This was then followed with sending letters to relevant stakeholders requesting for input (if any) regarding the company. There were no comments received during this process.

During the on-site audit, the audit team had also consulted the estates stakeholders.

No complain received from this consultation process and only positive comment received from the stakeholders. Among the stakeholders attending the consultation process includes:

## 2.5 Hectarage/ Mill Capacity Statement

Estate		
Total Area (ha)	Planted (Ha)	FFB Production
107.15	107.15	3075.24

## 2.6 Location

Estate/Mill /Smallholder/SPOC	GPS Location	Location
RICH & SUCCESS SDN BHD	N 5.7065 E117.6392	LA 81081341, Mukim Luang Manis Labuk/Sugut Sabah

## 3.1 Certification Details

Date of certificate Issued	17/03/2020
Certificate Validity	27/02/2020- 26/02/2025
Other Sustainability Certification	NIL

## 3.2 Audit Finding

Finding Grading	Total	Status
Minor	4	Open/ <u>Closed</u>
Major	0	N/A
Observation	0	N/A

## 3.3 Summary of Audit Finding

Based on the results of this audit, it is concluded that the certified organization has established, implemented and maintained its management system in line with the requirement of the standard of **MS 2530:3 2013 General Principle for Oil Palm Plantation and Organised Smallholders.**

This Audit is based on interviews, observation and sampling of activities within the organization management system and does not follow that no non-conformity exists in areas where none has been reported

**4.1 Recommendation**

Therefore, the audit team recommended the following action:

	Minor NCR(s) recorded. Corrective action plan has been accepted. Verification of the NCR(s) to be carried out in the next audit.
	No NCR recorded. Recommended for certification.
	Note: Minor NCRs raised in the audit which are not addressed in the subsequent audit shall be upgraded to major NCRs
	Major NCR(s) recorded. Evidence of implementation of the corrective actions have been provided and accepted by the audit team. The NCR(s) have been satisfactorily closed out
	Recommended for certification

Appendix 1: Estate/Mill Map

